Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2129/2
Work Order Type: Weatherization
Audit Name: A C Beard

CLIENT INFORMATION

Client Name: BEARD, AC Address:

Client ID: 50005DE2129

Alt. Client ID:

CLIENT CONTACT INFORMATION

BEARD, AC (901) 465-9773 Applicant/Person of Record

AGENCY INFORMATION

Agency: Delta Human Resource Agency

Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Alt. Client ID:

Measures

		lace 24" x 20" Crawl S _l	pace Door		Componer	ıts			Inspected
Col	mment				Estimated	1		Actual	
# N	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 C	Other	Door Only- Material	Each	1					
2 L	.abor	Labor		1					
3 C	Other	Unit- Material	Each	1					
4 L	.abor	Labor		1					
Oth	ner Detail								
				_] []	Cub Total	
	ield Notes:		/	vieasur	e Sub Total:		•	Sub Total:	
	easure 2 Rep	lace Broken 24" x 28" I	Pane in WI)#9	Componer Estimated			Actual	Inspected
# A	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Vindows	Material	Each	1		70.00			70.00
2 L	.abor	Labor		1					
Oth	ner Detail								
				_]]	Doct. To (a)	
			/	Measur	e Sub Total:		•	Sub Total:	
F	ield Notes:								

Measure 3 Inf	iltration Redctn			Componen	ts		ı	Inspecte
Door S Weath	Sweep FRONT 2 erstrip Door FRONT 2 Sweep STORAGE RM erstrip Door STORAGE R be and weatherstrip attic s							
·	•			Estimated	ı		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail						1		
						1	Sub Total:	
Field Notes:			Measur	e Sub Total:			oud rotal.	
	/H Pipe Insulation			e Sub Total:	nts		L	Inspecte
Measure 4 DW	/H Pipe Insulation			L			L	Inspected
Measure 4 DW	VH Pipe Insulation Description / Comment	Units		Componen		Qty	L.	Inspected Total
Measure 4 DV Comment				Componen Estimated	<u> </u>		Actual	
Measure 4 DV Comment # Material / Labor	Description / Comment	Units	Qty	Componen Estimated	<u> </u>		Actual	
Measure 4 DV Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 4 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 4 DV Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	

Alt. Client ID:

				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1486					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Measure 6 Repla	ace Htg. System			Componen	ts HS1		ı	Inspected
				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipment	Space Heater - 30 kBtu/h NG Existing, 26 - 37 kBtu/h NG Post	Each	1					
Labor	Space Heater - 30 kBtu/h NG Existing, 26 - 37 kBtu/h NG Post	Each	1					
Other Detail			1			1		
			Measure	e Sub Total:			Sub Total:	
Field Notes:								

		Monitor is Needed			Componen	ts			Inspecte
C	omment				Estimated	1		Actual	
¥	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
O	Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Measure 8 Fix I	mproper Venting (Cloth	nes Dryer	<u> </u>	Componen	ts			Inspecte
	Measure 8 Fix I	mproper Venting (Cloth	nes Dryer)	Componen Estimated			Actual	Inspecte
C		mproper Venting (Cloth Description / Comment	nes Dryer <i>Unit</i> s	Qty	•		Qty		Inspecte
C #	omment	Description / Comment			Estimated	1	Qty	Actual	
C (omment Material / Labor Health and Safety	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
C (#	omment Material / Labor Health and Safety Items	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
C # 1 1 2	omment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
C (#	omment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated	1		Actual	

Commont $ADD 2 $	/entilation Inadequate (STATIC VENTS	(Attic)		Componen	ts			Inspecte
Comment ADD 2 3	TATIC VENTS			Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
] []		
			Measur	e Sub Total:]	Sub Total:	
Measure 10 Smo	ke Detector is Needed			Componen	ts		1	Inspecte
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
	Description / Comment Smoke detector	<i>Units</i> Each	Qty 1			Qty		Total
Health and Safety Items						Qty		Total
Health and Safety Items	Smoke detector		1			Qty		Total
2 Labor	Smoke detector		1			Qty		Total
1 Health and Safety Items2 Labor	Smoke detector	Each	1					Total
1 Health and Safety Items2 Labor	Smoke detector	Each	1	Unit Cost			Unit Cost	Total
1 Health and Safety Items2 LaborOther Detail	Smoke detector	Each	1	Unit Cost			Unit Cost	Total
Health and Safety Items Labor Other Detail	Smoke detector	Each	1	Unit Cost			Unit Cost	Total